

EP067 3M™ SPEEDGLAS™ OUTER PROTECTION PLATE,

9100/G5-01/03, STANDARD

DESCRIPTION

- Highlights: -Helps protect the welding filter from welding sparks and spatter -Replacement part -For use with 3M™ Speedglas™ Welding Helmets and Filters -Outer Protection Plate 3M™ Speedglas™ Outside Protection Plates are designed for use with 3M™ Speedglas™ Welding Helmets and Filters and protect the welding filter from sparks and spatter. 3M™ Speedglas™ Outside Protection Plates are a replacement part designed to be used when the original has been damaged or worn out. Help protect your welding filter from sparks and spatter by ensuring that your Outside Protection Plate is functioning properly.



SIZE AVAILABILITY

ONE SIZE - ONE SIZE

Specifications/Technical Data	
Brand	3M
Compatible Welding Helmet	9100 Series
Part Type	Consumable
Product series	9100 MP, 9100 MP-Lite, 9100, Speedglas 9100 Air, 9100 FX, 9100 FX-Air
Product Type	Outside Protection Plate
Recommended application	Welding, Metal Processing, Metal Repair, Grinding